











# HSAL HSWD




**VILJANDI**  
windows • doors







1.




2.




3.




4.





5.




6.





7.








1.




2.




3.




4.




5.




1.




2.





3.





4.



5.



E3	1 x	E4	1 x
			
		M4 x 45	

S	2 x	K	3 x
