












- (EE) SIRGE SERVAGA SISEUKSED
(GB) NON-REBATED INTERNAL DOORS
(DK) INDVENDIGE DØRE
(SE) INNERDÖRRAR
(NO) INNERDØRER




VILJANDI
windows • doors



















2




3




[illegible]


6R




6L 1.




2.







3.





4.



5.





1.

2.

3.

K2

-K2

K2

K2

K2

4 x

5,0 x 80

Technical drawing of a door assembly showing the installation of L1 hinges. The main drawing shows a door with multiple hinges labeled L1. An inset shows a close-up of a hinge being installed into a pre-drilled hole with a diameter of 16mm. A legend at the bottom right shows the L1 hinge and the number 8.

